

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, February 28, 2019	Project Contact:	Brian Clauto
Spread H: Roanoke County Franklin County	STA 12972+00 – 12941+41 STA 12994+02 – 13021+14	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- Clearing
 Rough Grading
 Trench Excavation
 Pipe Assembly, Testing & Installation
 Backfilling and Grade Restoration
 Final Grading & Stabilization
 Other:

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments:

- Streams / wetlands inspected included: S-Y8, S-Y7, W-Y2, S-Y9, S-IJ43 and W-IJ36.

Recommended Corrective Action:

Deadline: Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: *Marshall Willis*

Date: 02/28/2019

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, February 28, 2019

Fig. 1: **STA 12968+00** – No ground disturbance.



Fig. 2: **STA 12965+00** – No ground disturbance.



Fig. 3: **S-Y8** – No ground disturbance.



Fig. 4: **S-Y8** – No ground disturbance.



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, February 28, 2019

Fig. 5: W-Y2 – No ground disturbance.



Fig. 6: S-Y7 – No ground disturbance.



Fig. 7: S-Y7 – No ground disturbance.



Fig. 8: S-Y7 – No ground disturbance.



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, February 28, 2019

Fig. 9: STA 12955+01 – No ground disturbance.



Fig. 10: S-IJ43 – No ground disturbance.



Fig. 11: STA 12998+00 – Area stabilized.



Fig. 12: STA 13021+14 – Area stabilized.

