FIELD INSPECTION

Project Name:	**Mountain Valley Pipeline**	**Inspector:**	**Matthew Grant**
Inspection Date:	**Tuesday, March 26, 2019**	**Project Contact:**	**Brian Clauto**
Spread: Roanoke County AR 288 AR 289 MP 246 St12993-13030 MP 240 St12870 Montgomery County AR 279 MP 235 St12453-12451	**Spread H**	**Weather (Wet/Dry/Rain):**	**Dry**

STAGE OF CONSTRUCTION: (Check all that apply)

☐ Clearing ☐ Rough Grading ☐ Trench Excavation ☐ Pipe Assembly, Testing & Installation

☐ Backfilling and Grade Restoration ☐ Final Grading & Stabilization ☒ Other: Dormant

		Yes	No	N/A
1	Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?	☒	☐	☐
2	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?	☒	☐	☐
3	Areas of offsite sediment deposition were observed?	☐	☒	☐

Comments:

- Inspected designated streams and wetlands included: W-KL1, W-Q11, W-IJ10, S-Q20, S-G24, W-ST2PEM. ECD were in place near all the streams / wetlands, no impacts were observed at the time of the inspection.
- W-IJ10 has had road gravel removed.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:___ ___ Date: _4/9/19

FIELD INSPECTION PHOTO LOG

Project Name: **Mountain Valley Pipeline** **Date:Tuesday, March 26, 2019**

- Fig. 1 W-IJ10 road gravel has been removed

- Fig. 2 St#12451+00 ECD's in place

- Fig. 3 AR279 ECD's in place and functioning

- Fig. 4 Near S-G24 clean water diversion has been installed and functioning