

## FIELD INSPECTION REPORT

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Matthew Grant
<b>Inspection Date:</b>	Thursday, March 5, 2020	<b>Project Contact:</b>	Brian Clauto,
<b>Spread H: Montgomery</b>	MP 232.5-231.5 MP 228.5-229.2 AR MN276.02, MN270 ATWS 1163, 1162	<b>Weather:</b>	Dry

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- Tree Felling     
  Clearing/Grubbing     
  Grading     
  Trenching     
  Stringing/Welding  
 Lowering/Backfilling     
  Final Grading     
  Temp. Stabilization     
  Perm. Stabilization     
 Dormant

- |  | Yes                                 | No                                  | N/A                      |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

- Comments: Inspected the following resources: S-MM15, S-MM14, S-MM13, S-MM11
- ECD's were in place at crossings and appeared to be functioning.

**Routine Maintenance:** (72-Hour Deadline from Notification)  
- N/A

**Ineffective Controls:** (24-Hour Deadline from Notification)  
- N/A

**Recommended Corrective Action:** N/A

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:** \_\_\_\_\_  \_\_\_\_\_

**Date:** Thursday, March 5, 2020

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Thursday, March 5, 2020

- Figure 1: Near MP 232.5 ECD's are in place and area has been stabilized with vegetation and matting.



- Figure 2: Near MP 232.1 temporary permanent bars have been installed along with CFS bars.



- Figure 3: Near MP 228.5 area remains stabilized with blanket matting and vegetation.



- Figure 4: At designated crossing S-MM15, ECD's are in place.

