

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Thursday, March 7, 2019	Project Contact:	Brian Clauto
Spread: Franklin County MP 246-247	Spread H	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | |
|--|--|---|--|
| <input type="checkbox"/> Clearing | <input type="checkbox"/> Rough Grading | <input type="checkbox"/> Trench Excavation | <input type="checkbox"/> Pipe Assembly, Testing & Installation |
| <input type="checkbox"/> Backfilling and Grade Restoration | <input type="checkbox"/> Final Grading & Stabilization | <input checked="" type="checkbox"/> Other: <u>Dormant</u> | |

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |


Comments:

- Inspected designated streams included: S-RR18, WRR4, S-G26, S-G27. ECD were in place near all the streams, no impacts were observed at the time of the inspection.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:  Date: 3-7-19

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, February 7, 2019

- Fig. 1 Slope near St#13026+00 has been stabilized with matting



- Fig. 2 Designated wetland W-RR4 and stream S-RR18 are protected with no impacts observed.



- Fig. 3 Designated stream S-G27 is protected with no impacts observed.



- Fig. 4 Designated stream S-G26 is protected with no impacts observed.

