

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Wednesday, April 17, 2019	Project Contact:	Brian Clauto
Spread: Montgomery County MP227-228 St#12009-12035	Spread H	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- Clearing Rough Grading Trench Excavation Pipe Assembly, Testing & Installation
 Backfilling and Grade Restoration Final Grading & Stabilization Other: Dormant

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |


Comments:

- Inspected designated streams and wetlands included: S-G36, S-G39, S-G40, S-G26, S-G38 ECD were in place near all the streams / wetlands, no impacts were observed at the time of the inspection.
- St#12009-12035 controls between these stations were in place and functioning.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:  Date: 5-6-19

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, April 17, 2019

<p>▪ Fig. 1 Designated stream S-G36</p> <p style="text-align: center;">South East Elevation</p> <p>☉ 325°NW (T) ☉ 37°16'6"N, 80°18'48"W ±164.1ft ▲ 1503ft</p> 	<p>▪ Fig. 2 Designated stream S-G39</p> <p style="text-align: center;">North West Elevation</p> <p>☉ 156°SE (T) ☉ 37°15'54"N, 80°18'31"W ±32.8ft ▲ 1670ft</p> 
<p>▪ Fig. 3 Designated stream S-G40</p> <p style="text-align: center;">North West Elevation</p> <p>☉ 142°SE (T) ☉ 37°15'54"N, 80°18'27"W ±164.1ft ▲ 1420ft</p> 	<p>▪ Fig. 4 Designated stream S-G38</p> <p style="text-align: center;">North West Elevation</p> <p>☉ 125°SE (T) ☉ 37°17'13"N, 80°17'43"W ±11289.9ft ▲ 1749ft</p> 