

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Thursday, April 4, 2019	Project Contact:	Brian Clauto
Spread AR270.01 AR270 MP228-229 ST#12071-12118 MP231 St12233	Spread H	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | |
|--|--|---|--|
| <input type="checkbox"/> Clearing | <input type="checkbox"/> Rough Grading | <input type="checkbox"/> Trench Excavation | <input type="checkbox"/> Pipe Assembly, Testing & Installation |
| <input type="checkbox"/> Backfilling and Grade Restoration | <input type="checkbox"/> Final Grading & Stabilization | <input checked="" type="checkbox"/> Other: <u>Dormant</u> | |

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments:

- Inspected designated streams and wetlands included: S-MM15, S-MM14, S-MM13, SMM-11, S-F15, W-F9-PFO, S-F16A&B. ECD were in place near all the streams / wetlands, no impacts were observed at the time of the inspection.
- St#12071-12118 ECD's were in place and functioning.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Matthew Grant Date: 4/9/19

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, April 4, 2019

- Fig. 1 Near S-MM 15, area has been stabilized and ECD's are in place



- Fig. 2 Near S-MM13, area has been stabilized and ECD's are in place



- Fig. 3 CWD in place and functioning at St#12003+00



- Fig. 4 Near St#12233+77 area has been stabilized

