

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, June 18, 2019

Fig. 1 ECD controls were in place during pipe install near St12201+05




Fig. 2 ECD controls were in place during pipe install near St12209+00



Fig. 3. ECD controls are in place at designated stream S-001



Fig. 4 ECD controls are in place at designated stream S-C21

