

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Wednesday, June 19, 2019	Project Contact:	Brian Clauto
Spread: Franklin County MP247 St13067 MP251 St13261 MP252 St13312 St13343-13352 MP254 St13415+36	Spread H	Weather (Wet/Dry/Rain):	Wet

STAGE OF CONSTRUCTION: (Check all that apply)

- Clearing
 Rough Grading
 Trench Excavation
 Pipe Assembly, Testing & Installation
 Backfilling and Grade Restoration
 Final Grading & Stabilization
 Other: bore sites & dormant area

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |


Comments:

- Inspected designated streams and wetlands included: W-RR4, W-K11, S-G26, S-G27, S-GH7, S-RR08, S-RR09, W-IJ2-PSS, S-IJ3, S-IJ2, S-IJ1, W-IJ1.
- ECD devices were installed as well as dewatering devices at bore sites.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.


Inspector Signature: _____  _____ Date: 6-24-19

FIELD INSPECTION PHOTO LOG


Project Name: Mountain Valley Pipeline

Date: Wednesday, June 19, 2019

- Fig. 1 ECD controls are in place at the bore pit for designated streams S-G26 & S-G27



- Fig. 2 ECD dewatering structure in place for bore pit area for designated streams S-G26 & S-G27



- Fig. 3 ECD dewatering structure in place for bore pit area for designated streams S-G26 & S-G27



- Fig. 4 ECD controls are in place at designated streams S-G26 & S-G27 and bore pits.

