

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Monday, July 1, 2019	Project Contact:	Brian Clauto
Spread: Roanoke County AR 288 Franklin County MP247 St13067 MP230 St12193+45 ATWS 704A AR MN 275	Spread H	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- Clearing Rough Grading Trench Excavation Pipe Assembly, Testing & Installation
 Backfilling and Grade Restoration Final Grading & Stabilization Other: bore sites & dormant areas

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments:

- Inspected designated streams and wetlands included: W—IJ10, W-K11,W-Q11, S-Q20, S-G26, S-G27, SC21,S-OO11
- No impacts to streams or wetlands were observed.
- ECD devices were installed as well as dewatering devices at bore site.
- ATWS 704A is currently in use; ATWS 704 is not in use and has not been disturbed.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Matthew Grant Date: 7/22/19

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, July 1, 2019

Fig. 1 ECD controls are in place at the bore pit for designated streams S-G26 & S-G27



Fig. 2 ECD controls are in place for bore pit area for designated streams S-G26 & S-G27




Fig. 3. ECD dewatering structure in place for bore pit area for designated streams S-G26 & S-G27



Fig. 4. ATWS 704A and AR MN275 are currently being used ECD's are in place and effective.

