

## FIELD INSPECTION

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Matthew Grant
<b>Inspection Date:</b>	Thursday, July 18, 2019	<b>Project Contact:</b>	Brian Clauto
<b>Spread: Montgomery Co.</b> MN275 MP230 St12193+45-1200+27 <b>Franklin Co.</b> FR290 MP247 St13063 FR293.01 MP251.1	Spread H	<b>Weather (Wet/Dry/Rain):</b>	Dry

**STAGE OF CONSTRUCTION:** (Check all that apply)

- Clearing                     
  Rough Grading                     
  Trench Excavation                     
  Pipe Assembly, Testing & Installation  
 Backfilling and Grade Restoration                     
  Final Grading & Stabilization                     
  Other: Dormant & Bore pits

- |   |   | Yes                                 | No                                  | N/A                      |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed?   | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

**Comments:**

- Inspected designated streams included: S-001, S-C21, S-G26, S-G27, W-RR4, S-II4
- St12199 sump requires maintenance
- S-G26 & S-G27 bridge sidewalls require maintenance

**Recommended Corrective Action:** Maintain controls per the approved plan and annual standard and specs.

**Deadline:** Within 24 hr. notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:  Date: 7-30-19

## FIELD INSPECTION PHOTO LOG


**Project Name:** Mountain Valley Pipeline

**Date:** Thursday, July 18, 2019

- Fig. 1 St12199 sump requires maintenance



- Fig. 2 S-G26 & S-G27 bridge sidewalls require maintenance



- Fig. 3. ECD in place above designated stream S-C21

