

## FIELD INSPECTION

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Matthew Grant
<b>Inspection Date:</b>	Tuesday, July 23, 2019	<b>Project Contact:</b>	Brian Clauto
<b>Spread: Montgomery Co. MP228-229 St12070-12102+64</b>	Spread H	<b>Weather (Wet/Dry/Rain):</b>	Rainy

**STAGE OF CONSTRUCTION:** (Check all that apply)

- Clearing                       Rough Grading                       Trench Excavation                       Pipe Assembly, Testing & Installation  
 Backfilling and Grade Restoration                       Final Grading & Stabilization                       Other: Dormant

- |   |   | Yes                                 | No                                  | N/A                      |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed?   | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

**Comments:**

- Inspected designated streams included: MM-13, MM-14, MM-15
- During the inspection a rain event was occurring, controls were in place and appeared to be functioning.

**General Comment:** Conduct an inspection after rain event to ensure ECD's are maintained per the annual standard and specs.

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Matthew Grant Date: 8-5-19

# FIELD INSPECTION PHOTO LOG


Project Name: Mountain Valley Pipeline

Date: Tuesday, July 23, 2019


- Fig. 1 At St12070+00 slope remains matted and stabilized.



- Fig. 2 Designated stream MM15 crossing, ECD's in place and functioning.



- Fig. 3. Designated stream MM14 crossing, ECD's in place and functioning.



- Fig. 4. Designated stream MM13 crossing, ECD's in place and functioning.

