

## FIELD INSPECTION

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Marshall Willis
<b>Inspection Date:</b>	Monday, August 26, 2019	<b>Project Contact:</b>	Brian Clauto, Cory Chalmers
<b>Spread H: Montgomery County</b>	STA 12071+80 – 12190+85 MVP-MN-270	<b>Weather (Wet/Dry/Rain):</b>	Dry

**STAGE OF CONSTRUCTION:** (Check all that apply)

- Clearing                       Rough Grading                       Trench Excavation                       Pipe Assembly, Testing & Installation  
 Backfilling and Grade Restoration                       Final Grading & Stabilization                       Other:

- |   |   | Yes                      | No                                  | N/A                      |
|---|---|--------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed?   | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

**Comments:** Inspected the following resources: S-MM15, S-MM14, S-MM13, S-MM12, S-F15, S-F16AB, S-C29, S-C24 and S-C25.

STA 12126+00: Maintain CFS/wattles.  
 STA 12130+00 to 12187+00: Stabilize stockpiles.

**Recommended Corrective Action:** Install and maintain all controls per the approved plans and PSS&S.

**Deadline:** Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: *Marshall Willis*

Date: 08/26/2019

# FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Monday, August 26, 2019

Fig. 1: **STA 12071+00** – Controls in place. Area stabilized with erosion matting and seed.



Fig. 2: **STA 12126+00** – CFS/wattle maintenance needed.



Fig. 3: **STA 12130+00 to 12187+00** – Stockpile stabilization needed.



Fig. 4: **STA 12190+85** – Bradshaw Road crossing. Controls in place. Stabilized with erosion fabric and seed.

