

## FIELD INSPECTION

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Marshall Willis
<b>Inspection Date:</b>	Wednesday, August 28, 2019	<b>Project Contact:</b>	Brian Clauto, Cory Chalmers
<b>Spread H:</b> Roanoke County Franklin County	STA 12703+08 – 12715+31 STA 13415+51 – 13342+67	<b>Weather (Wet/Dry/Rain):</b>	Dry

**STAGE OF CONSTRUCTION:** (Check all that apply)

- Clearing     
  Rough Grading     
  Trench Excavation     
  Pipe Assembly, Testing & Installation  
 Backfilling and Grade Restoration     
  Final Grading & Stabilization     
  Other: Dormant

- |   |   | Yes                                 | No                                  | N/A                      |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed?   | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

**Comments:** Inspected the following resources: S-RR11, S-RR09, S-RR08, S-IJ1, and S-IJ3.

- STA 13374+00: Maintain P1.
- STA 13374+00: Maintain SSF.
- STA 13374+00: Stabilize slope.
- STA 13343+00: Clean up/remove trash.

**Recommended Corrective Action:** Install and maintain all controls per the approved plans and PSS&S.

**Deadline:** Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: *Marshall Willis*

Date: 08/28/2019

# FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Wednesday, August 28, 2019

Fig. 1: **STA 13374+00** – P1 undermined, maintenance needed.



Fig. 2: **STA 13374+00** – SSF maintenance needed.



Fig. 3: **STA 13374+00** – Repair and stabilize slope.



Fig. 4: **STA 13343+00** – Clean up/remove personal trash and waste.

