

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Friday, September 13, 2019	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Montgomery County Roanoke County	STA 12422+32 – 12435+16 STA 12437+00 – 12448+00 MVP-RO-279.01	Weather (Wet/Dry/Rain):	Rainy

STAGE OF CONSTRUCTION: (Check all that apply)

- Clearing Rough Grading Trench Excavation Pipe Assembly, Testing & Installation
 Backfilling and Grade Restoration Final Grading & Stabilization Other: Dormant

- | | | Yes | No | N/A |
|---|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-NN16.

Recommended Corrective Action: N/A.

Deadline: Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: *Marshall Willis*

Date: 09/13/2019

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Friday, September 13, 2019

Fig. 1: **STA 12425+00** – Controls installed. Diversion berm stabilized. ROW stabilization and seeding in progress.

Fig. 2: **Stream S-NN16** – Roanoke River crossing. No disturbance.

☉ 128°SE (T) ● 37°14'6"N, 80°11'58"W ±164.1ft ▲ 871ft



☉ 254°W (T) ● 37°14'0"N, 80°11'52"W ±16.4ft ▲ 1167ft



Fig. 3: **STA 12433+00** – Stabilization in progress in ATWS 725.

Fig. 4: **STA 12638+00** – Controls in place. Area stabilized with hydro-mulch and erosion blanket.

☉ 85°E (T) ● 37°14'1"N, 80°11'52"W ±32.8ft ▲ 1231ft



☉ 81°E (T) ● 37°11'34"N, 80°10'25"W ±16.4ft ▲ 3436ft

