

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Thursday, September 26, 2019	Project Contact:	Brian Clauto
Spread: Montgomery Co. AR MN 278.01 MP237.3-235.7	Spread H	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- Clearing Rough Grading Trench Excavation Pipe Assembly, Testing & Installation
 Backfilling and Grade Restoration Final Grading & Stabilization Other: winter stabilization

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments:

- Inspected designated streams & wetlands included: W-CD11-UP, S-EF19
- ECD's were in place for active construction and functioning at designated streams.
- St12539+15 SSF requires maintenance
- St12533+62 CFS requires maintenance
- Areas of sediment that have been previously reported include: S-EF19, St12529+64, St12530+21, W-EF5PFO, S-EF20a

Recommend Corrective Action: Maintain and install all controls per the approved plan and specs

Deadline: Within 24hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Matthew Grant Date: 10-9-19

FIELD INSPECTION PHOTO LOG


Project Name: Mountain Valley Pipeline

Date: Thursday, September 26, 2019

- Fig. 1 Slope leading to AR MN278.01 has been stabilized with matting.



- Fig. 2. St12539+15 SSF has a hole in it and requires maintenance.



- Fig. 3 St12533+62 CFS has a hole in it and requires maintenance.



- Fig. 4 St12496+00 pipe is being rock guarded.

