

## FIELD INSPECTION

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Marshall Willis
<b>Inspection Date:</b>	Friday, January 10, 2020	<b>Project Contact:</b>	Brian Clauto, Cory Chalmers
<b>Spread I: Franklin County</b>	STA 14411+04 – 14524+76 MVP-FR-317 ATWS 358/358A/527/359/1340/360	<b>Weather (Wet/Dry/Rain):</b>	Wet

**STAGE OF CONSTRUCTION:** (Check all that apply)

- Clearing                       Rough Grading                       Trench Excavation                       Pipe Assembly, Testing & Installation  
 Backfilling and Grade Restoration                       Final Grading & Stabilization                       Other: Dormant

- |   |   | Yes                                 | No                                  | N/A                      |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed?   | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

**Comments:** Inspected the following resources: S-GH36, S-KL17, S-GH37, S-GH38, S-GH37, S-GH39, S-G22, S-G23, S-G21 and S-G20.

**Recommended Corrective Action:** N/A

**Deadline:** Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: *Marshall Willis*

Date: 1/10/2020

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Friday, January 10, 2020

Fig. 1: **STA 14414+00** – Controls in place and functioning properly.



Fig. 2: **Wetland W-GH16** – Controls in place and functioning properly.



Fig. 3: **STA 14460+00** – Controls in place and functioning properly.



Fig. 4: **STA 14480+50** – Controls in place and functioning properly around Stream S-G22.

