

## FIELD INSPECTION

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Marshall Willis
<b>Inspection Date:</b>	Thursday, February 14, 2019	<b>Project Contact:</b>	Brian Clauto
<b>Spread I:</b> Franklin County Pittsylvania County	STA 13444 – 13498 STA 15673 STA 15854 - 15879	<b>Weather (Wet/Dry/Rain):</b>	Dry

**STAGE OF CONSTRUCTION:** (Check all that apply)

- Clearing                       Rough Grading                       Trench Excavation                       Pipe Assembly, Testing & Installation  
 Backfilling and Grade Restoration                       Final Grading & Stabilization                       Other:

- |   |   | Yes                      | No                                  | N/A                      |
|---|---|--------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed?   | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments:

- Streams / wetlands inspected included: S-IJ10, W-IJ6, S-IJ8, S-B6, W-G2, S-G2, and S-B2.
- CFS undermined at STA 13497.
- CFS full at STA 13497.
- Sediment deposition within wetland W-G2 at STA

**Recommended Corrective Action:** Maintain and install all controls per the approved plan and specs.

**Deadline:** Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: 

Date: 02/14/2019

# FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Thursday, February 14, 2019

<p>Fig. 1: <b>S-IJ10</b> - Controls in place.</p> <div style="border: 1px solid black; padding: 5px; margin-top: 10px;"> <p style="text-align: center; background-color: #cccccc; margin: 0;"><b>South West Elevation</b></p> <p style="text-align: center; margin: 0;"> <span style="font-size: small;">⊗ 46°NE (T)   ⊙ 37°5'20"N, 80°0'18"W ±32.8ft   ▲ 1285ft</span> </p>  <p style="text-align: right; font-size: x-small; margin: 0;">S-IJ10 14 Feb 2019, 08:40:18</p> </div>	<p>Fig. 2: <b>STA 13498</b> - Area stabilized.</p> <div style="border: 1px solid black; padding: 5px; margin-top: 10px;"> <p style="text-align: center; background-color: #cccccc; margin: 0;"><b>North East Elevation</b></p> <p style="text-align: center; margin: 0;"> <span style="font-size: small;">⊗ 245°SW (T)   ⊙ 37°5'19"N, 80°0'19"W ±98.4ft   ▲ 1406ft</span> </p>  <p style="text-align: right; font-size: x-small; margin: 0;">14 Feb 2019, 08:43:17</p> </div>
<p>Fig. 3: <b>STA 13497</b> – CFS undermined. CFS full.</p> <div style="border: 1px solid black; padding: 5px; margin-top: 10px;"> <p style="text-align: center; background-color: #cccccc; margin: 0;"> <span style="font-size: x-small;">NW   N   NE   E   SE</span>  <span style="font-size: x-small;">330   0   30   60   90   120</span> </p> <p style="text-align: center; margin: 0;"> <span style="font-size: small;">⊗ 48°NE (T)   ⊙ 37°5'18"N, 80°0'21"W ±98.4ft   ▲ 1467ft</span> </p>  <p style="text-align: right; font-size: x-small; margin: 0;">14 Feb 2019, 08:49:40</p> </div>	<p>Fig. 4: <b>STA 13476</b> – Area stabilized.</p> <div style="border: 1px solid black; padding: 5px; margin-top: 10px;"> <p style="text-align: center; background-color: #cccccc; margin: 0;"> <span style="font-size: x-small;">SW   W   NW   N</span>  <span style="font-size: x-small;">210   240   270   300   330   0</span> </p> <p style="text-align: center; margin: 0;"> <span style="font-size: small;">⊗ 286°W (T)   ⊙ 37°5'6"N, 80°0'37"W ±16.4ft   ▲ 1625ft</span> </p>  <p style="text-align: right; font-size: x-small; margin: 0;">13476 14 Feb 2019, 09:07:55</p> </div>

# FIELD INSPECTION PHOTO LOG


**Project Name:** Mountain Valley Pipeline

**Date:** Thursday, February 14, 2019

**Fig. 5: STA 13451 – Area stabilized.**



**Fig. 6: STA 15673 – ROW-post Earth Guard stabilization.**



**Fig. 7: W-G2 – Sediment deposition in wetland at STA 15852+59**



**Fig. 5: STA 15858 – ROW-pre Earth Guard application.**

