

## FIELD INSPECTION REPORT

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Marshall Willis
<b>Inspection Date:</b>	Tuesday, March 3, 2020	<b>Project Contact:</b>	Brian Clauto, Cory Chalmers
<b>Spread I: Pittsylvania County</b>	STA 15584+23 – 15647+03 ATWS 813/1445	<b>Weather:</b>	Rainy

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- Tree Felling     
  Clearing/Grubbing     
  Grading     
  Trenching     
  Stringing/Welding  
 Lowering/Backfilling     
  Final Restoration     
  Temp. Stabilization     
  Perm. Stabilization     
 Dormant

- |  | Yes                                 | No                                  | N/A                      |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

**Comments:** Inspected the following resources: W-MM9, S-CC1, W-MM8-PEM, W-MM8-PFO, S-CC3, S-P5 and S-IJ35-EPH.

**Recommended Corrective Action:** N/A

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:** 

**Date:** Tuesday, March 3, 2020

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Tuesday, March 3, 2020

**Figure 1: STA 15589+00** – Controls in place and functioning properly.



**Figure 2: Stream S-CC1** – Controls in place and functioning properly.



**Figure 3: Stream S-IJ35-EPH** – Controls in place and functioning properly.



**Figure 4: STA 15641+00** – Controls in place and functioning properly. Area stabilized with Earth-Guard.

