

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Friday, May 17, 2019	Project Contact:	Brian Clauto
Spread I: Pittsylvania County	STA 15826+88 – 15947+64	Weather (Wet/Dry/Rain):	Wet

STAGE OF CONSTRUCTION: (Check all that apply)

- Clearing Rough Grading Trench Excavation Pipe Assembly, Testing & Installation
 Backfilling and Grade Restoration Final Grading & Stabilization Other: Dormant

- | | | Yes | No | N/A |
|---|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-G2, W-G2, S-B2, S-H55 and S-H54.

- STA 15848+50 – Maintain P1, re-stabilize stockpile.
- STA 15868+70 – Sediment off ROW, upgrade ECDs.
- STA 15875+00 – Sediment off ROW, re-stabilize upslope areas.

Recommended Corrective Action: Maintain and install all controls per the approved plan and specs.

Deadline: Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: *Marshall Willis*

Date: 05/17/2019

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Friday, May 17, 2019

Fig. 1: STA 15826+84 – Controls in place. Area stabilized with Earth Guard.



Fig. 2: STA 15848+50 – Repair P1, stabilize stockpile.



Fig. 3: STA 15863+00 – Controls in place. Area stabilized with Earth Guard.



Fig. 4: STA 15868+70 – Sediment off ROW. Upgrade ECDs/repair as needed.



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Friday, May 17, 2019

Fig. 5: STA 15875+00 – Sediment off ROW.



Fig. 6: STA 15875+00 – Re-stabilize slope.



Fig. 7: STA 15924+00 – Controls in place.



Fig. 8: STA 15947+00 – Controls in place.

