

## FIELD INSPECTION

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Marshall Willis
<b>Inspection Date:</b>	Friday, May 24, 2019	<b>Project Contact:</b>	Brian Clauto
<b>Spread I: Franklin County</b>	STA 14018+47 – 14042+25 STA 14171+36 – 14209+88 STA 14311+57 – 14333+27	<b>Weather (Wet/Dry/Rain):</b>	Dry

**STAGE OF CONSTRUCTION:** (Check all that apply)

- Clearing                       Rough Grading                       Trench Excavation                       Pipe Assembly, Testing & Installation  
 Backfilling and Grade Restoration                       Final Grading & Stabilization                       Other: Dormant

- |   |   | Yes                                 | No                                  | N/A                      |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed?   | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: The following reseouces were inspected: S-KL39, S-KL52, S-F8 and S-GG4.

**Recommended Corrective Action:** N/A

**Deadline:** Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: *Marshall Willis*

Date: 05/24/2019

# FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Friday, May 24, 2019

Fig. 1: **STA 14030+00** – Controls in place.



Fig. 2: **STA 14197+00** – Controls in place.



Fig. 3: **STA 14311+00** – Controls in place.



Fig. 4: **STA 14322+00** – Controls in place.

