FIELD INSPECTION REPORT

Project Name:	**Mountain Valley Pipeline**	**Inspector:**	**Marshall Willis**
Inspection Date:	**Monday, June 29, 2020**	**Project Contact:**	**Brian Clauto, Cory Chalmers**
Spread I: **Franklin County**	**STA 13820+00 – 13892+50** **MVP-FR-302** **ATWS 346/347/1040/518/519/696**	**Weather:**	**Dry**

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

☐ Tree Felling ☐ Clearing/Grubbing ☐ Grading ☐ Trenching ☐ Stringing/Welding

☐ Lowering/Backfilling ☐ Final Restoration ☐ Temp. Stabilization ☐ Perm. Stabilization ☒ Dormant

		Yes	No	N/A
1.	Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?	☒	☐	☐
2.	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?	☒	☐	☐
3.	Areas of offsite sediment deposition observed?	☐	☒	☐

Comments: Inspected the following resources: S-C14, S-C16, S-C17, W-CD6, S-CD6 and W-CD5.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: **Monday, June 29, 2020**

FIELD INSPECTION PHOTO LOG

Project Name: **Mountain Valley Pipeline** **Date:** **Monday, June 29, 2020**

Figure 1: **Stream S-C16**– Controls in place and functioning properly around stream crossing. Area stabilized.

Figure 2: **STA 13855+00** – Controls in place and functioning properly. Area stabilized with straw and vegetation.

Figure 3: **STA 13880+00** – Controls in place and functioning properly. Area stabilized with straw and vegetation.

Figure 4: **Wetland W-CD5** – Controls in place and functioning properly around wetland crossing.