

## FIELD INSPECTION

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Marshall Willis
<b>Inspection Date:</b>	Wednesday, June 5, 2019	<b>Project Contact:</b>	Brian Clauto
<b>Spread I: Franklin County</b>	STA 13748+30 – 13826+95 STA 13627+40 – 13690+91	<b>Weather (Wet/Dry/Rain):</b>	Rainy

**STAGE OF CONSTRUCTION:** (Check all that apply)

- Clearing                       Rough Grading                       Trench Excavation                       Pipe Assembly, Testing & Installation  
 Backfilling and Grade Restoration                       Final Grading & Stabilization                       Other: Dormant

- |   |   | Yes                                 | No                                  | N/A                      |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed?   | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

**Comments:** Inspected the following resources: S-EF7, S-EF12, S-MM42, S-RR15, S-D23, S-D22, S-D20, S-E28, S-GH4/3, S-GH2 and S-E29.

STA 13767+10: Run-on bypassing CWD.  
 STA 13782+00: Maintain/repair P1.  
 STA 13793+96: Maintain/repair sump.

**Recommended Corrective Action:** Maintain and install all controls per the approved plans and PSS&S.

**Deadline:** Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: *Marshall Willis*

Date: 06/05/2019

# FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Wednesday, June 5, 2019

**Fig. 1: STA 13767+10** – Run-on bypassing CWD inlet.



**Fig. 2: STA 13782+00** – P1 undermined.



**Fig. 3: STA 13793+96** – Sump maintenance needed.



**Fig. 4: STA 13666+00** – Controls in place. Area stabilized outside travel lane.

