

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Wednesday, July 24, 2019	Project Contact:	Brian Clauto
Spread: Franklin Co. MP265-266 St14043-14061 MP255 St13498	Spread I	Weather (Wet/Dry/Rain):	Wet

STAGE OF CONSTRUCTION: (Check all that apply)

- Clearing Rough Grading Trench Excavation Pipe Assembly, Testing & Installation
 Backfilling and Grade Restoration Final Grading & Stabilization Other: Dormant

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments:

- Inspected designated stream included: S-YZ4, S-YZ5, S-IJ10
- Designated stream S-YZ4 and S-YZ5 have been cleaned of impacts.
- St14061-14043 requires additional stabilization of stockpiles and lower section of 2 tone on ROW noted on 7-18-19 inspection report.
- St14049+00 water bar flow path requires maintenance

Recommended Corrective Action: Maintain controls per the approved plan and annual standard and specs.

Deadline: Within 24 hr. notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Matthew Grant Date: 8-5-19

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, July 24, 2019

- Fig. 1 Designated stream crossing S-YZ5, ECD's in place and functioning.



- Fig. 2 Designated stream crossing S-YZ4, ECD's in place and functioning.



- Fig. 3 St14049+00 water bar flow path requires maintenance



- Fig. 4 St14061-14043 requires additional stabilization of stockpiles.



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, July 24, 2019

Fig. 5 Designated stream S-IJ10 ECD's and bridge in place and functioning.



Fig. 6 Designated stream S-IJ10 ECD's and bridge in place and functioning

