

## FIELD INSPECTION

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Marshall Willis
<b>Inspection Date:</b>	Monday, August 19, 2019	<b>Project Contact:</b>	Brian Clauto, Cory Chalmers
<b>Spread I: Franklin County</b>	STA 14018+47– 14042+25 MVP-MLV-31	<b>Weather (Wet/Dry/Rain):</b>	Dry

**STAGE OF CONSTRUCTION:** (Check all that apply)

- Clearing                       Rough Grading                       Trench Excavation                       Pipe Assembly, Testing & Installation  
 Backfilling and Grade Restoration                       Final Grading & Stabilization                       Other: Dormant

- |   |   | Yes                                 | No                                  | N/A                      |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed?   | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |

Comments: Inspected the following resources: S- KL39

STA 14019+91: Stabilize slopes and area surrounding MLV-31.  
 STA 14033+50 to 14034+50: Waterbar maintenance required.  
 STA 14034+50: Sediment off ROW.

**Recommended Corrective Action:** Maintain and install all controls per the approved plan and PSS&S.

**Deadline:** Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: *Marshall Willis*

Date: 08/19/2019

# FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Monday, August 19, 2019

Fig. 1: **STA 14019+91** – Stabilize slopes and area adjacent to MLV-31.



Fig. 2: **STA 14033+50 to 14034+50** – Maintain waterbars.



Fig. 3: **STA 14033+50 to 14034+50** – Maintain waterbars.



Fig. 4: **STA 14034+50** – Sediment off ROW.

