

## FIELD INSPECTION

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Matthew Grant
<b>Inspection Date:</b>	Tuesday, August 28, 2018	<b>Project Contact:</b>	Brian Clauto
<b>Spread:</b>	Spread I	<b>Weather (Wet/Dry/Rain):</b>	Dry

**STAGE OF CONSTRUCTION:** (Check all that apply)

- Clearing                       Rough Grading                       Trench Excavation                       Pipe Assembly, Testing & Installation  
 Backfilling and Grade Restoration                       Final Grading & Stabilization                       Other: \_\_\_\_\_

- |   |   | Yes                                 | No                                  | N/A                      |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed?   | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments:

- **Area 1** - Spread I, Franklin County, near Cahas Mountain Road, approximately MP 254 permanent water bars were being installed.
- **Area 2**- Spread I, Franklin County, near Grassy Hill Rd, approximately MP 259.40 temporary stabilization had been applied and maintenance had been conducted on conveyance channels.
- **Area 3**- Spread I, Franklin County, near Iron Ridge Rd, approximately MP 262.90 temporary stabilization had been applied.

**Deadline:**   N/A  

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:   Matthew Grant   Date:   9-17-18

## FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, August 28, 2018

Fig. 1  
Near MP 262 temporary stabilization had been applied.



Fig. 2  
Near MP 259 temporary stabilization has been applied.



Fig. 3  
Near MP 259 rock conveyance channels had been maintained.



Fig. 4  
Near MP 254 permanent waterbars were being installed

