

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Tuesday, August 4, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 13415+51 – 13444+93 STA 13539+00 – 13543+50 STA 13562+38 – 13575+21 ATWS 1351/1343/1342/1066/1416	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- Tree Felling
 Clearing/Grubbing
 Grading
 Trenching
 Stringing/Welding
 Lowering/Backfilling
 Final Restoration
 Temp. Stabilization
 Perm. Stabilization
 Dormant

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-IJ4, S-IJ8, W-II8, S-II7, S-II9, S-GH6 and W-GH2.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: 

Date: Tuesday, August 4, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, August 4, 2020

Figure 1: STA 13423+00 – Controls in place and functioning properly.

☉ 107°E (T) ☉ 37°5'29"N, 80°1'31"W ±32ft ▲ 1476ft



Figure 2: STA 13435+00 – Controls in place and functioning properly.

☉ 284°W (T) ☉ 37°5'25"N, 80°1'14"W ±16ft ▲ 1664ft



Figure 3: STA 13440+00 – Controls in place and functioning properly.

☉ 132°SE (T) ☉ 37°5'25"N, 80°1'11"W ±32ft ▲ 1712ft



Figure 4: STA 13542+00 – Controls in place and functioning properly.

☉ 86°E (T) ☉ 37°5'28"N, 79°59'27"W ±16ft ▲ 1249ft

