

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, September 25, 2019	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 13811+56 – 13876+00 STA 13758+00 – 13733+00	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- Clearing Rough Grading Trench Excavation Pipe Assembly, Testing & Installation
 Backfilling and Grade Restoration Final Grading & Stabilization Other:

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: W-CD5, S-CD6, W-CD6, S-C16, S-C17 and S-C14.

Recommended Corrective Action: N/A

Deadline: Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: *Marshall Willis*

Date: 09/25/2019

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, September 25, 2019

Fig. 1: **STA 13889+00** – Controls in place adjacent to W-CD5. Area stabilized.



Fig. 2: **STA 13846+78** – Controls in place around S-C16. Area stabilized except for active travel lane.



Fig. 3: **STA 13875+16** – Controls in place along S-C16.




Fig. 4: **STA 13745+00** – Controls in place. Final grading in progress. Actively hydro-seeding in this area.

