

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, September 3, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Pittsylvania County	Transco-Station	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- Tree Felling
 Clearing/Grubbing
 Grading
 Trenching
 Stringing/Welding
 Lowering/Backfilling
 Final Restoration
 Temp. Stabilization
 Perm. Stabilization
 Dormant

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: N/A.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: 

Date: Thursday, September 3, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, September 3, 2020

Figure 1: Transco-Station – Controls in place and functioning properly.

⊗ 269°W (T) ● 36°49'57"N, 79°20'36"W ±16ft ▲ 679ft



Figure 2: Transco-Station – SB-1 functioning properly.

⊗ 186°S (T) ● 36°49'55"N, 79°20'38"W ±16ft ▲ 630ft



Figure 3: Transco-Station – SB-1 functioning properly.

⊗ 48°NE (T) ● 36°49'53"N, 79°20'38"W ±16ft ▲ 628ft




Figure 4: Transco-Station – ST-2 functioning properly.

⊗ 304°NW (T) ● 36°50'1"N, 79°20'38"W ±16ft ▲ 661ft

