

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Stafford
Inspection Date:	Wednesday, July 11, 2018	Project Contact:	Brian Clauto
Spread:	Spread G	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- Clearing
 Rough Grading
 Trench Excavation
 Pipe Assembly, Testing & Installation
 Backfilling and Grade Restoration
 Final Grading & Stabilization
 Other: _____

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments:

Area 1 - Jefferson National Forest, MP 221.0 to 220.1 (station 11621+50 to 11670+64). This is the re-inspection of ESC measures required as noted in the area when released on July 3, 2018 to recover and move woody debris. The ROW was inspected for compliance with required ESC measures and no deficiencies were observed.

Area 2 – Area west of Hwy 42 near Winding Way station MP 212 to 212.8 (station 11237+47 to 11194+00). The ROW and one access road (MLV-25) was inspected for compliance with required ESC measures and no deficiencies were observed.

Area 3 - Mountain Lake Rd station, MP 210.8 to 211.3 (station 11157+29 to 11134+00). The ROW and one access roads (AR-GL-249) was inspected for compliance with required ESC measures and no deficiencies were observed.

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:  Date: 7-16-18

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, July 11, 2018

Fig. 1
Brush Mt looking towards Craigs Creek Rd (Area 1)



Fig. 2
Near Winding Way Dr, ahead of grade (Area 2)



Fig. 3
Area above Mountain Lake Rd, ahead of grade (Area 3)



Fig. 4