

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Stafford
Inspection Date:	Friday, July 6, 2018	Project Contact:	Brian Clauto
Spread:	Spread G	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- Clearing
 Rough Grading
 Trench Excavation
 Pipe Assembly, Testing & Installation
 Backfilling and Grade Restoration
 Final Grading & Stabilization
 Other: _____

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments:


Area 1 - Mount Tabor Road to Brush Mountain station 11789+02 to 11670+64. The ROW was inspected for compliance with required ESC measures and no deficiencies were observed.

Area 2 – Craig's Creek to Sinking Creek Mountain station 11621+50 to 11553+66. The ROW and two access roads (258.03 and 258.05) were inspected for compliance with required ESC measures and no deficiencies were observed.

Area 3 - Sinking Creek Mountain to Route 42 station 11553+66 to 11255+00. The ROW and five access roads (253.02, 256, 256.02, 258.01 and 258.02) were inspected for compliance with required ESC measures and no deficiencies were observed.

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:  Date: 7-16-18

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Friday, July 6, 2018

Fig. 1
Waterbar (Area 1)



Fig. 2
Area of work on Brush Mountain (Area 1)



Fig. 3
Looking up Sinking Creek Mt, ahead of grade (Area 2)



Fig. 4
Craigs Creek access road area (Area 2)



Fig. 5
Sinking Creek Mt, ahead of grade (Area 3)



Fig. 6
Ahead of grade (Area 3)



Fig. 7
Additional karst measures, ahead of grade (Area 3)



Fig. 8
Looking down to Rt 42 crossing, ahead of grade (Area 3)

