

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Thursday, October 11, 2018	Project Contact:	Brian Clauto
Spread: Montgomery County MP229 St#12111+76-12118 MP230 St#12192 MP235 St#12453 Roanoke County Laydown Yard 26	Spread H	Weather (Wet/Dry/Rain):	Wet

STAGE OF CONSTRUCTION: (Check all that apply)

- Clearing Rough Grading Trench Excavation Pipe Assembly, Testing & Installation
 Backfilling and Grade Restoration Final Grading & Stabilization Other: Stream Crossing

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments:

- **Area 1** – MP 229 St#12111+76-12118+76 ECD's are in place and functioning.
- **Area 2** – MP 230 St#12191 designated stream SC21 ECD's are in place and functioning.
- **Area 3** – MP 232 St#12283 ECD's are in place and functioning.
- **Area 4** – MP 235 St#12453 ECD's are in place and functioning.
- **Area 5** – Laydown yard 26 ECD's are in place and functioning.

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Matthew Grant Date: 11-5-18

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, October 11, 2018

Fig. 1
MP 230 St#12192 designated stream SC21 ECD's are in place.

South West Elevation

⊗ 66°NE (T) ● 37°15'6"N, 80°15'33"W ±32.8ft ▲ 1249ft



Fig. 2
MP 232 St#12283 matting in place at Reese Mtn.

South Elevation

⊗ 353°N (T) ● 37°15'3"N, 80°11'36"W ±4639.3ft ▲ 1494ft



Fig. 3
Route 11 crossing near St#12453 ECD's are in place.

South Elevation

⊗ 348°N (T) ● 37°14'1"N, 80°11'58"W ±4964.2ft ▲ 1184ft



Fig. 4
Laydown yard 26 in Roanoke County

South Elevation

⊗ 16°N (T) ● 37°16'16"N, 80°7'13"W ±656.2ft ▲ 1177ft

