

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Stafford
Inspection Date:	Tuesday, July 17, 2018	Project Contact:	Brian Clauto
Spread:	Spread H : Station 12054+42 to 12071+80 (Approximate MP 228.3-228.6)	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | |
|--|--|---|---|
| <input checked="" type="checkbox"/> Clearing | <input checked="" type="checkbox"/> Rough Grading | <input checked="" type="checkbox"/> Trench Excavation | <input checked="" type="checkbox"/> Pipe Assembly, Testing & Installation |
| <input type="checkbox"/> Backfilling and Grade Restoration | <input type="checkbox"/> Final Grading & Stabilization | <input type="checkbox"/> Other: _____ | |

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments:

This area included a section of ROW and one access road (MN-270). ESC measures on the ROW were inspected for compliance with required ESC measures and no deficiencies were observed.

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:  _____ Date: 7-20-18

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, July 17, 2018

Fig. 1
From 12065+00 going away downslope



Fig. 2
Sump and outlet 12061+00



Fig. 3

Fig. 4