

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, July 18, 2018

Fig. 1
Clean water diversion at 12093+00



Fig. 2
Stream and wetland crossing W-C12/W-C11, S-C33 at 12121+00



Fig. 3
Coming in side at 12145+00



Fig. 4
Stabilized stockpile at 12147+00



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, July 18, 2018

Fig.5
Going away side of 12147+00



Fig. 6
Water bar near 12051+00



Fig. 7
End treatment near 12051+00



Fig. 8
Coming in view from 12047+00

