

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Thursday, July 19, 2018	Project Contact:	Brian Clauto
Spread:	Spread H	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- Clearing
 Rough Grading
 Trench Excavation
 Pipe Assembly, Testing & Installation
 Backfilling and Grade Restoration
 Final Grading & Stabilization
 Other: _____

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments:

- **Area 1** - Spread H, Montgomery County, near Reese Mountain Road, approximately MP 232.46 station 12285+00 to approximately MP 232.6 station 12291+00.
- **Area 2**- Spread H, Montgomery County, near Catawba Road, approximately MP 227.6 station 12026+00 to approximately MP 227.7 station 12023+00.

These areas were inspected for compliance with required ESC measures and no deficiencies were observed.

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Matthew Grant Date: 7-23-18

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, July 19, 2018

Fig. 1 Station 12286+00 water bar installed



Fig. 2 near Station 12287+ 93 area has been stabilized



Fig. 3 Below station 12026+51 area has been stabilized



Fig. 4 Station 12026+51 slope drain installed

