

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Stafford
Inspection Date:	Tuesday, July 3, 2018	Project Contact:	Brian Clauto
Spread:	Spread H	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- Clearing
 Rough Grading
 Trench Excavation
 Pipe Assembly, Testing & Installation
 Backfilling and Grade Restoration
 Final Grading & Stabilization
 Other: _____

- | | | Yes | No | N/A |
|---|---|--------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments:

Bent Mountain Road/Blue Ridge Parkway, Areas between Stations 12994+18 to 13033+25 include two sections of ROW separated by undisturbed areas on Blue Ridge Parkway and one access road (MVP-FR-289). Contact DEQ for re-inspection.

Deficiencies included:

-Slope and compaction of water bars

NOT RELEASED FOR WORK

Deadline: Prior to release for work

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:  Date: 7-16-18