

## FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Wednesday, September 26, 2018	Project Contact:	Brian Clauto
Spread: Franklin County	Spread I	Weather (Wet/Dry/Rain):	Wet

**STAGE OF CONSTRUCTION:** (Check all that apply)

- Clearing                       Rough Grading                       Trench Excavation                       Pipe Assembly, Testing & Installation  
 Backfilling and Grade Restoration                       Final Grading & Stabilization                       Other:

- |   |   | Yes                                 | No                       | N/A                      |
|---|---|-------------------------------------|--------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed?   | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |

Comments / Observations:

- **Area 1** – near MP 261 additional controls have been installed and escaped sediment has been removed where off site property permission has been given.

**Deadline:**   N/A  

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:   Matthew Grant   Date:   11/5/18

## FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, September 26, 2018

<p>Fig. 1 Near MP 261 ECD in place</p> <div style="text-align: center; background-color: #cccccc; padding: 2px;"><b>North Elevation</b></div> <div style="background-color: #cccccc; padding: 2px; font-size: small;">             📍 183°S (T) 📍 37°4'6"N, 79°55'22"W ±16.4ft ▲ 1083ft         </div> 	<p>Fig. 2 Near MP 261 ECD in place</p> <div style="text-align: center; background-color: #cccccc; padding: 2px;"><b>South West Elevation</b></div> <div style="background-color: #cccccc; padding: 2px; font-size: small;">             📍 35°NE (T) 📍 37°4'6"N, 79°55'21"W ±16.4ft ▲ 1092ft         </div> 
<p>Fig. 3 Near MP 261 ECD in place</p> <div style="text-align: center; background-color: #cccccc; padding: 2px;"><b>North West Elevation</b></div> <div style="background-color: #cccccc; padding: 2px; font-size: small;">             📍 142°SE (T) 📍 37°4'7"N, 79°55'23"W ±16.4ft ▲ 1112ft         </div> 	<p>Fig. 4 Near MP 261 ECD in place</p> <div style="text-align: center; background-color: #cccccc; padding: 2px;"><b>South East Elevation</b></div> <div style="background-color: #cccccc; padding: 2px; font-size: small;">             📍 300°NW (T) 📍 37°4'4"N, 79°55'20"W ±16.4ft ▲ 1108ft         </div> 