

## FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Thursday, July 12, 2018	Project Contact:	Brian Clauto
Spread:	Spread H	Weather (Wet/Dry/Rain):	Dry

**STAGE OF CONSTRUCTION:** (Check all that apply)

- Clearing                     
  Rough Grading                     
  Trench Excavation                     
  Pipe Assembly, Testing & Installation  
 Backfilling and Grade Restoration                     
  Final Grading & Stabilization                     
  Other: \_\_\_\_\_

- |   |   | Yes                      | No                                  | N/A                      |
|---|---|--------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed?   | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments:

- Area 1- Spread H, near Catawba Rd. in Montgomery Co, station 12026+00 (MP 227.6) to 12023+00 (MP 227.7). This area included a small section of the ROW (two water bars and end treatments) which were observed to be deficient.

NOT RELEASED FOR WORK

**Deadline:**     Prior to release to work    

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:     *Matthew Grant*     Date:     7-16-18

## FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, July 12, 2018

Fig. 1 Inadequate water bar near station #12024+00



Fig. 2 Water bar with missing end treatment near station # 12024+00

