

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	August 22 & 23, 2018	Project Contact:	Brian Clauto
Spread:	Spread H	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- Clearing
 Rough Grading
 Trench Excavation
 Pipe Assembly, Testing & Installation
 Backfilling and Grade Restoration
 Final Grading & Stabilization
 Other: _____

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments:

- **Area 1** - Spread H, Montgomery County, near Reese Mountain Road, approximately MP 232 station 12285+75 to approximately MP 232.6 blanket matting had been installed.
- **Area 2**- Spread H, Franklin County, near Webster Corner Rd, approximately MP 253.1 station 13366+34 on going waterbar install construction and stabilization.
- **Area 3**- Spread H, Montgomery County, approximately MP 227.7 designated stream S-G36 crossing stabilization in place.

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: *Matthew Grant* Date: 9-4-18

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, August 23, 2018

Fig. 1
Near St# 12285+75 blanket matting installed



Fig. 2
Near St# 13366+34 waterbar install



Fig. 3
S-G36 crossing re contoured per the approved plan



Fig. 4