

## FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Steve Mumpower
Inspection Date:	Monday, July 23, 2018	Project Contact:	Brian Clauto, Randy Clark
Spread:	Spread H	Weather (Wet/Dry/Rain):	Wet

**STAGE OF CONSTRUCTION:** (Check all that apply)

- Clearing     
  Rough Grading     
  Trench Excavation     
  Pipe Assembly, Testing & Installation  
 Backfilling and Grade Restoration     
  Final Grading & Stabilization     
  Other: \_\_\_\_\_

- |   |   | Yes                                 | No                                  | N/A                      |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed?   | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: 13250+00 to 13262+00 (Approximate MP 250.9 to 251.2): This area was inspected for compliance with required ESC measures and no deficiencies were observed.

**Deadline:** \_\_\_\_\_ N/A \_\_\_\_\_

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Stephen Mumpower      Date: 7-23-18

# FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, July 23, 2018

<p>Fig. 1</p> <p><b>East Elevation</b></p> <p>☉ 270°W (T) ● 37.115574°N, 80.060577°W ±32.8ft ▲ 1434ft</p>  <p>Flat water bars fixed and maintained MBP</p> <p>MVP Speed I 23 Jul 2018, 10:06</p>	<p>Fig. 2</p>
<p>Fig. 3</p>	<p>Fig. 4</p>