FIELD INSPECTION

Project Name:	**Mountain Valley Pipeline**	**Inspector:**	**Matthew Stafford**
Inspection Date:	**Tuesday, July 17, 2018**	**Project Contact:**	**Brian Clauto**
Spread:	**Spread H : Station 12054+42 to 12071+80 (Approximate MP 228.3-228.6)**	**Weather (Wet/Dry/Rain):**	**Dry**

STAGE OF CONSTRUCTION: (Check all that apply)

☒ Clearing ☒ Rough Grading ☒ Trench Excavation ☒ Pipe Assembly, Testing & Installation

☐ Backfilling and Grade Restoration ☐ Final Grading & Stabilization ☐ Other: _____

		Yes	No	N/A
1	Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?	☒	☐	☐
2	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?	☒	☐	☐
3	Areas of offsite sediment deposition were observed?	☐	☒	☐

Comments:

This area included a section of ROW and one access road (MN-270). ESC measures on the ROW were inspected for compliance with required ESC measures and no deficiencies were observed.

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: _____ Date: 7-20-18

FIELD INSPECTION PHOTO LOG

Project Name: **Mountain Valley Pipeline** **Date: Tuesday, July 17, 2018**

Fig. 1
From 12065+00 going away downslope

Fig. 2
Sump and outlet 12061+00

Fig. 3

Fig. 4