FIELD INSPECTION REPORT

Project Name:	**Mountain Valley Pipeline**	**Inspector:**	**Dane Blevins**
Inspection Date:	**Saturday, July 28, 2018**	**Project Contact:**	**Brian Clauto, Randy Clark**
Spread:	**Spread H**	**Weather (Wet/Dry/Rain):**	**Dry**

STAGE OF CONSTRUCTION: (Check all that apply)

☐ Clearing ☒ Rough Grading ☐ Trench Excavation ☐ Pipe Assembly, Testing & Installation

☐ Backfilling and Grade Restoration ☐ Final Grading & Stabilization ☐ Other: _____

		Yes	No	N/A
1	Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?	☒	☐	☐
2	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?	☒	☐	☐
3	Areas of offsite sediment deposition were observed?	☐	☒	☐

Comments: STA 13116+00-13120+17 (Approximate MP 248.4 to 248.5): This area was inspected for compliance with required ESC measures and no deficiencies were observed.

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: _____ Date: 7-30-18

FIELD INSPECTION PHOTO LOG

Project Name: **Mountain Valley Pipeline** **Date:Saturday, July 28, 2018**

Fig. 1

Fig. 2

Fig. 3

Fig. 4